

Condition Report / Motor Vehicle Checklist

Trucks / Motor Vehicles

Description: **SPOT VAC.** ID # **598331** Date **2/6/20**

This checklist is a record of a visual inspection which identifies defects reasonably known to B&J Equipment Pty Ltd at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. B&J Equipment Pty Ltd does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on B&J Equipment Pty Ltd which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The B&J Equipment Pty Ltd Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.bjequip.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/Model: **HINO FS1K.** Engine / Motor - Make / Model: **HINO R13C-TF**
 Year: **2004.** Engine Serial Number: **K1300T10394**
 Serial Number: **JHDFSIKLNKX10789** Meter Reading: **353968.**
 Comments: **REGC AD 19 PT**

Feature:

Pickup Flat Bed Tipper Boom Tanker Other
 Drive System: 2WD 4WD Power Take Off: Yes No
 Tare: Gross: **52000** GVM: **24000**

Overall Appearance:

Control Station/Operator Station: Good Fair Poor
 Sheet metal/Fiberglass Condition: Good Fair Poor
 Paint: Good Fair Poor
 Lights: Good Fair Poor

Operator Station: Good Fair Poor N/A
 Seat Condition: Good Fair Poor N/A
 Steering Controls: Good Fair Poor N/A
 Powertrain Controls: Good Fair Poor N/A
 Hydraulic Controls: Good Fair Poor N/A

Safety Devices: Yes No N/A
 Gauges: Yes No N/A
 Air Conditioner: Yes No N/A
 Heater: Yes No N/A
 Horn: Yes No N/A
 Reverse Alarm: Yes No N/A
 Odometer: Yes No N/A
 Wiper: Yes No N/A

Engine: Power: Diesel Electric

Does it start?: Yes No
 Did it need to be jumped?: Yes No
 Acceptable Power: Yes No
 Unusual Noises: Yes No
 Temperature / Overheating: Yes No

Chassis: Good Fair Poor Inoper Missing N/A
 Bumpers: Good Fair Poor Inoper Missing N/A
 Windshield Condition: Good Fair Poor Inoper Missing N/A
 Trailer Connections: Good Fair Poor Inoper Missing N/A
 Work Body Function: Good Fair Poor Inoper Missing N/A
 Trailer Electrical Connections: Good Fair Poor Inoper Missing N/A
 Trailer Brakes: Good Fair Poor Inoper Missing N/A
 Switches: Good Fair Poor Inoper Missing N/A

Tyre Condition: Left - Front, Left - Rear, Right - Front, Right - Rear

Brand: ADVANCE	Brand: BOTO	Brand: ADVANCE	Brand: BOTO
Size: 195/80R22.5	Size: 11R22.5	Size: 195/80R22.5	Size: 11R22.5
Condition: 85%	Condition: 80%	Condition: 85%	Condition: 80%

Any other known issues, faults: