Traffic (Arrow boards, traffic lights and VMS) Asset # 11861 Service Job # _200824-75 ILTON VSLS Description This checklist is a record of a visual inspection which identifies defects reasonably known to DSsH at the time, it should only be used as a guide. The buyer should rety on their own inspection and assessment of the equipment. The equipment is used and sold as is. DSsH does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or compiles with all relevant laws. Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on . DSsH which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. DSsH Terms Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or st www.divsaleshire.com.aas General Information: *** Copy Data Plate information in this section *** Make/ Model Engine/Motor - Make/Model 2016 140-35-CHD4 Year Engine Serial Number Serial Number Meter Reading Comments: Features: List features or options for the machine: Battery Peck (Electric) Soler Panel Number of Batteries **Battery Size** Fuel Tank Capacity Overall Appearance: Comments: Poor Control Station\Operator Station Sheet metal\Fiberglass Condition Paint Lights Control Station Operates Comments: N/A No Operator Controls Gauges Operational? Controller Engine or Electric Motor: Gas Power. Diesel No Yes Comments: Does it start? Did it need to be jumped? Acceptable Power Umisual Noises Chassis: Comments: Fair Poor Inoper Missing NIA Good Landing Gear / Outriggers Frame Condition Trailer Lights Trailer Electrical Connections Trailer Brakes Switches Arrow Board Message Center Soler Panel Battery and Connections Tyre Condition: Left - Front Left - Roar Comments: Brand- LONGWAY LONGLINAY Brand-8514 Size-Condition- DIC Condition-Any other known issues, faults: AST-CL-011A Asset inspection Checklist - Traffic 12/07/2023 issue 1.1

Diversified Sales & Hire Condition Inspection Checklist